



PA Series

Variable Area Flowmeter

- Field indicated Flow meter for use without power supply
- Designed to fit into small spaces for easy installation in general factory piping lines and panels
- Easily check the flow of fluid (bubble, color, etc.)

PA-82 Series General Specifications

Size	1/8"
Process Connection	PT
Measuring Fluid	Water, Air
Accuracy	±5.0 % F.S
Fluid Temperature	Max. 60 °C
Max. Pressure	Max. 6 kgf/cm ² .G

MODEL CODE

PA-82	-	□	-	□	Specification
		W			Measured for Water
		A			Measured for Air
				1 ~ 3	Refer to Water Flow ranges Rear to Rear
				1 ~ 6	Refer to Air Flow ranges Rear to Rear

FLOW RANGES

Model	Measure Range	Model	Measure Range
	Water (L/min)		Air (NL/min)
PA-82-W-1	0.3 - 1.5	PA-82-A-1	0.5 - 5
		PA-82-A-2	1 - 10
PA-82-W-2	1 - 2	PA-82-A-3	5 - 25
		PA-82-A-4	5 - 50
PA-82-W-3	0.5 - 3	PA-82-A-5	7 - 70
		PA-82-A-6	10 - 100

DIMENSIONS DRAWING

