


Weighing Management PC Program

- Held by a variety of programs.
- Appropriate development program at the production site.
- Using a variety of features and convenient.
- Printing function, operation, and records, data and statistics.

Tester Weighing program

CH.1	1.5618	kgf
CH.2	3.2058	kgf
CH.3	5.0397	kgf
CH.4	7.7805	lbf
CH.5	9.8071	lbf
CH.6	11.665	lbf



PDN20 Program

The first screenshot shows the 'DC VIEWER' window with 'DATA VIEWER' selected. It displays a large digital scale reading of '0.5442 kgf'. Below the reading are controls for '1 Hz (1 Sample/S)', 'Save', 'Stop', and a timer showing '00:00:00.0'. A 'Memory' button and an 'Exit' button are also present.

The second screenshot shows the 'Memory Data' window. It has 'From' and 'To' fields both set to '1'. A 'Load' button is highlighted with a red circle. Below is a table with multiple empty rows. At the bottom are 'Convert' and 'Exit' buttons.

Truck Scale Program

The first two screenshots show the truck scale interface. The top part features a large digital display showing '700kg' with a truck image in the background. Below this is a detailed data table with columns for various parameters like weight, date, and time.

The third screenshot shows a 'Weight Report' window. It contains several tables of data, including 'Weight Report', 'Data Weighing Report', 'Weighing List per Customer', and 'Data Weighing List per Customer'. The tables contain columns for customer names, weights, and dates.